



Western Michigan University  
ScholarWorks at WMU

---

Legacy Scout Tickets from Pure Oil Company

---

8-20-2021

**MGRRE\_PureOilScoutTickets\_Hense, Frank F. & L.  
E.\_4\_21159082520000**

MGRRE  
*Western Michigan University*

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

---

#### WMU ScholarWorks Citation

MGRRE, "MGRRE\_PureOilScoutTickets\_Hense, Frank F. & L. E.\_4\_21159082520000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 10292.  
<https://scholarworks.wmich.edu/pure/10292>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



---

MGRRE\_PureOilScoutTickets\_Hense, Frank F. & L. E.\_4\_21159082520000

API 21159082520000

Permit Number 8252

Lease Name Hense, Frank F. & L. E.

Well Number 4

County Van Buren

Township 01S

Range 14W

Section 14

2021 DEQ or Pure co\_name Jetter Drilling Company

Pure Number 676

Latitude 42.38552

Longitude -85.91473

THE PURE OIL COMPANY

DATE November 27, 1940

## LOCATION REPORT

No. 676STATE MichiganCOUNTY Van BurenDIST BloomingtonTWP. BloomingtonSEC. 14TOWN 1 SRANGE 14 WWELL No. 44 (SERIAL No. 676) FARMPREC. Frank F. and L. E. Hence

ACRES

NAME OF STREAM OR WATERS

QUADRANGLE NE SW NWOPERATOR Jetter Drilling CompanyMap Bloomington Township, Van Buren CountyBloomington - Van Buren

Feet from North Line of Farm

330 330

East " " "

South " " "

990 990

West " " "

Feet from North Line of Section

990 990

East " " "

South " 1/4 "990 990

West " " "

## LEGEND

○ LOCATION

① RIG

⊕ DRILLING

☼ GAS WELL

● OIL WELL

● SMALL OIL WELL

⊙ DRY HOLE

◆ DRY SHOWING OIL


⊙ DRY SHOWING GAS

⊙ ABANDONED LOCATION

☼ ABANDONED GAS WELL

● ABANDONED OIL WELL

NOTE: Below make tracing from map. (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.



REMARKS:

SIGNED

Subintendent or Foreman.



